

SAV 112

Pfautler PH sensor type PH 04/K

Pfautler

DESCRIPTION

Range 0 - 10 PH

T° : 0 - 140°C

P -1 + 9 b



PHOTOS

