

SAV 112

Sonde de mesure de PH Pfaudler type PH 04/K

Pfaudler

DESCRIPTION

0 - 10 PH

T° : 0 - 140°C

Pression -1 + 9 b



PHOTOS

