

VOV 045

Vanne papillon DN50 - Etat neuf

Gemu

DESCRIPTION

Joint EPDM

Materiau 1.4408

Commande manuelle



PHOTOS

